

CEN25LA100

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Overview (Courtesy of FAA)



Photograph 2 - Throttle Arm and Cable End (Courtesy of FAA)