

CEN25LA109

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing damage (Courtesy of FAA)