

CEN25LA150

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Wrinkling of lower fuselage (Courtesy of FAA)**



**Photograph 2 - Landing gear penetration of floor (Courtesy of FAA)**