

CEN25LA153

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of Classic Aero Maintenance)



Photograph 2 - Right Wing Side View (Courtesy of Classic Aero Maintenance)