

CEN25LA179

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged left wing (Courtesy of pilot)



Photograph 2 - Interior of outboard end of left wing (Courtesy of pilot)