

CEN25LA196

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N755SD left side (Courtesy of airport manager)



Photograph 2 - N755SD right side (Courtesy of airport manager)



**Photograph 3 - N755SD propeller & lower engine cowling
(Courtesy of airport manager)**



**Photograph 4 - N755SD nose landing gear / belly damage
(Courtesy of airport manager)**