

CEN25LA202

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Glider front left (Courtesy of FAA)



Photograph 2 - Left wing damage (Courtesy of FAA)



Photograph 3 - Inboard left wing damage (Courtesy of FAA)