

CEN25LA225

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Side view of airplane (Courtesy of FAA)



Photograph 2 - Rear view of airplane (Courtesy of FAA)



Photograph 3 - Engine exhaust blockage as found (NTSB Photo)



Photograph 4 - Steel baffle plate removed from tailpipe (NTSB Photo)



Photograph 5 - Accident airplane muffler (NTSB Photo)