

CEN25LA230

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the front of the airplane inside of a hangar (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the left side of the airplane inside of a hangar (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the right side of the airplane inside of a hangar (courtesy of the Federal Aviation Administration)



**Photograph 5 - View of the substantial damage sustained to the left horizontal stabilizer
(courtesy of the Federal Aviation Administration)**