


CEN25LA278

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on runway 9 (Courtesy of FAA)



Photograph 2 -Damage to left wing (Courtesy of FAA)



Photograph 3 - Damage at aft fuselage/empennage (Courtesy of FAA)



Photograph 4 - Left main landing gear lateral pushrod (Courtesy of FAA)