



Jennifer Rodi
Senior Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 7/22/25

Subject: CEN25LA278

Contact: [REDACTED] - Pilot

The pilot stated that he was landing on runway 9 and reported that he observed 3 green light indications consistent with the landing gear being extended. During the landing roll the left main landing gear started to fold. The pilot heard the landing gear pump turn on, at which time the landing gear collapsed completely. The airplane came to rest on the left wing on the north side of the runway.