

CEN25LA294

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Elevator Damage (Courtesy of FAA)



Photograph 2 - Left Flap Damage (Courtesy of FAA)