

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA299

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident Site (Courtesy of FAA)



Photograph 2 - Right wing strut damage (Courtesy of FAA)



Photograph 3 - Engine mount tube damage (Courtesy of FAA)