

CEN25LA322

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)




Photograph 2 - Oil under fuselage (Courtesy of FAA)



Photograph 3 - Engine left side (Courtesy of FAA)




Photograph 4 - No. 2 piston (Courtesy of FAA)



Photograph 5 - No. 2 piston (Courtesy of FAA)



Photograph 6 - No. 2 cylinder (Courtesy of FAA)



Photograph 7 - No. 2 cylinder (Courtesy of FAA)



Photograph 8 - No. 2 exhaust valve stem (Courtesy of FAA)



Photograph 9 - No. 2 exhaust valve stem (Courtesy of FAA)



Photograph 10 - No. 2 exhaust valve springs and push rods (Courtesy of FAA)