


CEN25LA332

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of USAFA Aero Club)



Photograph 2 - Rib Damage - Emphasis Added (Courtesy of USAFA Aero Club)