

CEN25LA333

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident site (Courtesy of APA Airport Ops)**



**Photograph 2 - Accident site (Courtesy of APA Airport Ops)**



**Photograph 3 - Tailwheel position before landing (Courtesy of pilot)**