

CEN25LA342

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Right wing damage (Courtesy of FAA)