

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA375

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane after it was recovered to an upright position at the accident site.
(Courtesy of Local Law Enforcement)**



Photograph 2 - Rudder Damage (Courtesy of FAA)



Photograph 3 - Right-Wing Lift Strut Damage (Courtesy of FAA)