

CEN25LA389

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter at accident site (FAA photo)



Photograph 2 - Helicopter at accident site (FAA photo)



Photograph 3 - Tail boom (FAA photo)



Photograph 4 - Tail rotor blade fragment (FAA photo)



Photograph 5 - Tail rotor assembly (FAA photo)



Photograph 6 - Tail boom / vertical stabilizers (FAA photo)