

CEN25LA399

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of Federal Aviation Administration)



Photograph 2 - Right Wing Root Damage (Courtesy of Federal Aviation Administration)



Photograph 3 - Right Wing Leading Edge Damage (Courtesy of Airport Manager)



Photograph 4 - Terminal Building Damage (Courtesy of Airport Manager)



Photograph 5 - Terminal Building Damage (Courtesy of Airport Manager)