

CEN25LA403

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantial damage to rudder (Courtesy of FAA)