

CEN25LA406

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of FAA)



Photograph 2 - Approach end of airstrip (Courtesy of FAA)



Photograph 3 - Underside of airplane during recovery (Courtesy of FAA)



Photograph 4 - Broken structural tube (Courtesy of FAA)