

CEN26LA003

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Empennage Damage (Courtesy of FAA)



Photograph 2 - Front View (Courtesy of FAA)