



Brian Rutt  
Air Safety Investigator  
AS-CEN

**Date:** November 5, 2025

**Subject:** CEN26LA025

**Contact:** Inspector [REDACTED], FAA

Inspector [REDACTED] reported that N5865P was brought into a hangar after it experienced a gear up landing in Eau Claire, WI. The circuit breaker for the landing gear was found tripped, and the landing gear linkage was disconnected from extending the gear manually during recovery operations. The airplane was placed on jacks, the landing gear link was reconnected, and the breaker was reset. The landing gear was cycled five times with no anomalies noted. The landing gear warning horn and position indicator light functioned as outlined in the maintenance manual. There was no damage found to the landing gear motor or linkage. The landing gear was well lubricated and functioned normally. ///END OF STATEMENT///