

CEN26LA047

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage and Wing Damage (Courtesy of Owner)



Photograph 2 - Lower Right Wing (Courtesy of Owner)