

CEN26LA055


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of FAA)



Photograph 2 - Accident airplane (Courtesy of FAA)



Photograph 3 - Broken engine mount (Courtesy of FAA)



Photograph 4 - Bent wing strut (Courtesy of FAA)



Photograph 5 - Bent wing strut (Courtesy of FAA)