

CEN26LA069

INVESTIGATION PHOTOGRAPHS




Picture 1 Airplane at Rest in Brush (Courtesy of the FAA)



Picture 2 Damage to Outer Right Wing (Courtesy of the FAA)



Picture 3 Collapsed Nose Landing Gear (Courtesy of the FAA)



Picture 4 Fuel Vent (Courtesy of the FAA)



Picture 5 Right Fuel Tank Vented Fuel Cap (Courtesy of the FAA)