

CEN26LA074

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of Airport Authority)



Photograph 2 - Aircraft in hangar at examination time (Courtesy of NTSB)




Photograph 3 - Engine with cowling removed (Courtesy of NTSB)



Photograph 4 - Spark plugs (Courtesy of NTSB)




Photograph 5 - Mixture linkage with severed safety wire (Courtesy of NTSB)



Photograph 6 - Position of mixture arm with fuel screen removed (Courtesy of NTSB)



Photograph 7 - Mixture cable slippage (Courtesy of NTSB)



Photograph 8 - Fuel manifold top removed, no fuel noted (Courtesy of NTSB)