

CEN26LA081

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Accident site (Courtesy of FAA)



Photograph 3 - Empennage damage (Courtesy of FAA)