

CEN26LA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the right side of the airplane in the water (courtesy of the pilot)



Photograph 2 - View of the left side of the airplane in the water (courtesy of the pilot)



**Photograph 3 - Front view of the airplane on the ramp after it was recovered from the water
(courtesy of the Federal Aviation Administration)**



Photograph 4 - View of the substantial damage sustained to the right wing (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the fuel sample obtained from the right wing fuel tank. The red arrow shows water contamination (courtesy of the Federal Aviation Administration)