

CEN26LA113

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Profile photo and nose gear swept aft (Courtesy of flight school)



Photograph 2 - Taxiway sign impacted by left wing (Courtesy of flight school)



Photograph 3 - Left wing damage (Courtesy of flight school)



Photograph 4 - Left wing spar damage (Courtesy of director of maintenance)



**Photograph 5 - Damage includes lower engine mount, propeller, and nose wheel steering rods
(Courtesy of director of maintenance)**