

CEN26LA117

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N5071K in hangar (Courtesy of owner)




Photograph 2 - Left profile of damages to airplane (Courtesy of owner)



Photograph 3 - Left side fuselage damages (Courtesy of owner)



Photograph 4 - Showing bent aft fuselage structure (Courtesy of owner)



Photograph 5 - Tailwheel bent off center (Courtesy of FAA)