

CEN26LA122

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (courtesy of operator).



Photograph 2 - Damage to right horizontal stabilizer and elevator (courtesy of operator).