

CEN26LA150

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N2785K at K61(Courtesy of owner)



Photograph 2 - Left wing damage (Courtesy of owner)