

CEN26LA180

INVESTIGATION PHOTOGRAPHS



Image 1 - Google Earth view of accident site with labels (Courtesy of FAA)



Power line view from end of Airstrip

Photograph 1 - Powerlines viewed from the end of the airstrip (Courtesy of FAA)



Photograph 2 - Airplane inverted and burned (Courtesy of FAA)



Photograph 3 - Right wing (Courtesy of FAA)



Photograph 4 - Left wing (Courtesy of FAA)



Photograph 5 - Tail (Courtesy of FAA)