

CEN26LA198

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fractured Engine Mount (Courtesy of FAA)