

CEN26LA233

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident glider vertical stabilizer (Courtesy of operator)



Photograph 2 - Accident glider rudder damage (Courtesy of operator)



Photograph 3 - Accident glider composite damage (Courtesy of operator)