

CEN26LA244

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane during the assembly work inside of the hangar (courtesy of the air racing team mechanic)



Photograph 2 - View of the airplane during the engine run up in front of the hangar (courtesy of the air racing team mechanic)



Photograph 3 - View of the fuselage and the engine at the accident site (courtesy of the air racing team mechanic)



Photograph 4 - View of the empennage at the accident site (courtesy of the air racing team mechanic)



Photograph 5 - View of the cockpit at the accident site (courtesy of the air racing team mechanic)



Photograph 6 - View of the right wing at the accident site (courtesy of the Federal Aviation Administration)



Photograph 7 - View of the left wing at the accident site (courtesy of the Federal Aviation Administration)



Photograph 8 - View of the propeller at the accident site (courtesy of the Federal Aviation Administration)



Photograph 9 - View of the pilot's airplane flight helmet at the accident site (courtesy of the Federal Aviation Administration)