

CEN26LA304

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Scene (Courtesy of the FAA)



Photograph 2 - Engine mount damage (Courtesy of the FAA)