



Customer Unit Findings Report

<u>Record #:</u>	74107	<u>Work Order:</u>	RS23-74107	
<u>RMA #:</u>	RS/4107	<u>Part Number:</u>	066-50008-0409*HON*OHC	
<u>Customer Number:</u>	00088	<u>Part Description:</u>	OUTLINE ASSY, RTA-4B	
<u>Customer Name:</u>	JetBlue Airways	<u>Ship Part Number:</u>		<u>Work Scope:</u> Tested
<u>Customer PO:</u>	2819653	<u>Series:</u>		<u>Receive Date:</u> 13 Dec 2023
<u>CAR:</u>		<u>Serial Number:</u>	RTA4B-16169	<u>Reship Date:</u>
<u>Initial Findings At Receipt:</u>	No FAA/EASA ADs. Tamper seals and dust cap intact. P/C/W SR 066-50008-34-153 MOD 25 (Rev 0, dated 4 MAR 2015) but was not identified. Pin 2 to p 7 measure 33 ohms. MOD 1-20 & 24. SW MOD 1, and Database 4. First time in the shop.			
<u>Customer Stated Reason For Return:</u>				
<u>Findings:</u>	Unit was inspected, tested, disassembled IAW CMM 34-41-36 (REV 13, dated:10 JAN 2023). The Unit passed preliminary testing. Unit previously complies with mod 25 IAW SR 066-50008-34-153 MOD 25 (Rev 0, dated 4 MAR 2015), the "25" on the mod plate will be marked.			
<u>Summary Of Actions:</u>	Unit was tested IAW CMM 34-41-36 (REV 13, dated:10 JAN 2023). The Unit passed all test requirements. The "25" on the mod plate was marked IAW SR 066-50008-34-153 MOD 25 (Rev 0, dated 4 MAR 2015).			