



737-9/-900ER MED Plug Enhancements
Subject to final certification




Six Additional Safety Features Added





New Retention Arm Assemblies

- Two assemblies prevent the plug from translating upward and becoming misaligned from fuselage stop fittings.
- If Retention Arm is not in the properly stowed position, it interferes with the installation of the interior sidewall panel

Open



Closed



Enhanced Primary Retention Features

- Four existing bolts securing plug to fuselage now permanently attached to plug via safety wire 'lanyard'
- Lanyards allow for plug installation and removal, but provide visual indications if bolts are not re-installed.

Any future 737-10 MED Plug designs will incorporate similar enhancements.