

DCA25LA085

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Lower fuselage damage near tail.



Photograph 2 - Tail skid.



Photograph 3 - Tail skid.



Photograph 4 - Lower fuselage damage near tail.



Photograph 5 - Drain mast damage.