

Damage Report

Date of Occurrence: 18-July-2025 (Local)

Aircraft Type: 787-10

Tail No.: JA986A


Aircraft Serial No.: 67000

Aircraft Manufacture Date: 17-July-2025


JA986A LH Wing Tip Damage



LH Wing Raked Wing Tip Assembly



Damage Overview (bottom view)



#1 Removable Wing Tip Assy

The removable tip is severed on the outboard edge.




#2 Aft Position Light



The Aft Position Light Assembly is severed.

#3 Raked Wing Tip Assembly

All components common to the leading edge of the Raked Wing Tip are bent, gouged, severed, and/or delaminated throughout the assembly. Additional locations of lower panel damage with disbond.




Wing Lower Shown



Wing Lower Shown

Outboard
FWD



Visible damage area

Wing Upper Shown



#4 Wing Tip FWD Position Light Assembly

The bullnose has multiple areas of scratches and the lense covers are cracked and gouged.

#5 Wire Harness - Aft Position Light

Damage of Aft position light wire harness is suspect.

