

DCA26LA102

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to AFT Right Cargo Door and Frame (Courtesy of Alaska Airlines)



Photograph 2 - Damage to Door Frame (Courtesy of Alaska Airlines)



Photograph 3 - View of Airplane on Ramp (Courtesy of Alaska Airlines)