



Photo 1 – Minor damage to right wing. (Source Endeavor Air)



Photo 2 – Right-wing leading-edge slat damage. (Source Endeavor Air)



Photo 3 – Minor damage to left wing. (Source Endeavor Air)



Photo 4 – Left-wing leading-edge slat damage. (Source Endeavor Air)