

A close-up photograph of a metal bellcrank assembly. The assembly consists of several metal arms and a central pivot point. A hexagonal nut is visible on one of the arms. Two arrows point to specific areas: one points to a small hole in the metal, and the other points to a channel in the metal.

MISSING BUSHINGS
AND SCREW

CENTERING CHANNEL

07/14/2011