



RECORD OF CONVERSATION

Carrol A. (Corky) Smith
Air Safety Investigator
Eastern Region

Date: August 4, 2011

art, Insurance Adjuster

NTSB Accident Number: ERA11LA438

Narrative:

Mr. Hart stated the left engine tachometer reading at the accident site was 0460.03 hours. The right engine tachometer reading at the accident site was 0552.24 hours. The HOBBS meter indicated 0046.7 hours.