



Photo 1: Digital Photograph Provided by FAA. View Depicting the Engine Assembly During the Postaccident Investigation.