



Photo 2 - View of Damage to Tail Rotor Driveshaft Cover and Severed Driveshaft