



Photo 2. Severed Tail Rotor Drive Shaft (Photo Courtesy of Air Force Fun Inc.)